

GLOVES

Flux Cored Glove



- 16" wing thumb welding gloves.
- Half welts.
- Double split leather palm patch and strap back.
- Kevlar stitching.

Part No	Description
FC1716L	Flux Cored Glove Large
FC1716XL	Flux Cored Glove X Large

Arcforce Glove



- 16" wing thumb welding gloves.
- Half welts.
- Kevlar stitching.

Part No	Description
AF1716L	Cow Hide Glove Large
AF1716XL	Cow Hide Glove X Large

Pigskin Glove



- 16" Pigskin welding gauntlet.
- Good heat resistance.
- Offers full forearm protection.

Part No	Description
P1716	Pigskin Glove Large

TIGMASTER® Pigskin Tig Glove



- No leading finger seam.
- Allows tight comfortable fit and maximum feel.

Part No	Description
P2104	Glove Large
P2104XL	Glove X Large

Goatskin Tig Glove



- Split cow hide cuff.
- Maximum softness and feel with hard wearing value.
- Extra pulse protection.

Part No	Description
AFGTIGL	Goatskin Glove Large
AFGTIGXL	Goatskin Glove X Large
AFGTIGXXL	Goatskin Glove XX Large


Pigskin Riggers Glove



- Soft and supple.
- Hard wearing.
- Excellent abrasion resistance.

Part No	Description
P1000	Pigskin Rigger Glove Large

Glove Saver



- Welding glove saver.
- Aluminium outer on thumb and hand back.
- Leather palm.

Part No	Description
GL777SVRL	Glove Saver Large
GL777SVRXL	Glove Saver X Large

Cool Back Hand Pads



- Protects the back of welder's gloves from weld spatter and high radiant heat.
- Helps to increase weld time when exposed to high heat.

Part No	Description
GL777	Back Hand Pad Elastic
GL777V	Back Hand Pad Velcro